

Table 2.5: Percentage distribution of damaged** housing units in affected DS divisions* by material used for construction: Ampara District

Affected DS Division	Material used for roof				Material used for wall				Material used for floor				Total
	Permanent	Temporary	NS [□]	Total	Permanent	Temporary	NS [□]	Total	Permanent	Temporary	NS [□]	Total	
	%	%	%	%	%	%	%	%	%	%	%	%	
Kalmuni	83.8	16.0	0.2	100.0	89.1	10.7	0.2	100.0	96.3	3.5	0.2	100.0	7815
Sainthamaruthu	93.7	6.1	0.2	100.0	95.8	4.0	0.2	100.0	96.4	3.4	0.2	100.0	2719
Karathivu	91.7	8.1	0.2	100.0	94.6	5.2	0.2	100.0	96.9	2.9	0.2	100.0	1931
Ninthavur	85.6	14.3	0.1	100.0	89.6	10.2	0.2	100.0	90.5	9.3	0.2	100.0	1674
Addalachchenai	64.8	35.0	0.2	100.0	67.7	32.1	0.2	100.0	76.9	22.9	0.2	100.0	592
Akkaraipattu	74.0	26.0	-	100.0	78.6	21.4	-	100.0	83.3	16.7	-	100.0	950
Alayadiwembu	50.3	48.7	1.0	100.0	53.1	45.9	1.0	100.0	69.7	29.0	1.3	100.0	328
Thirukkovil	59.8	39.9	0.3	100.0	70.0	29.8	0.2	100.0	79.4	20.4	0.2	100.0	2953
Pothuvil	44.6	55.1	0.3	100.0	58.7	41.0	0.3	100.0	73.6	26.0	0.4	100.0	2206
Lahugala	26.1	73.9	-	100.0	47.8	52.2	-	100.0	73.9	26.1	-	100.0	33
Total	76.5	23.3	0.2	100.0	82.7	17.1	0.2	100.0	89.5	10.2	0.3	100.0	21201

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.