

Table 2.5: Percentage distribution of damaged\*\* housing units in affected DS divisions\* by material used for construction: Batticaloe District

Affected DS Division	Material used for roof				Material used for wall				Material used for floor				Total
	Permanent	Temporary	NS <sup>□</sup>	Total	Permanent	Temporary	NS <sup>□</sup>	Total	Permanent	Temporary	NS <sup>□</sup>	Total	
	%	%	%	%	%	%	%	%	%	%	%	%	
Koralai Pattu North	19.1	80.9	-	100.0	23.1	76.9	-	100.0	30.2	69.8	-	100.0	1749
Koralai Pattu	45.5	54.4	0.1	100.0	53.9	46.0	0.1	100.0	59.6	40.1	0.3	100.0	1334
Koralai Pattu South	15.5	84.5	-	100.0	27.6	72.4	-	100.0	39.7	60.3	-	100.0	67
Eravur Pattu	23.7	76.3	-	100.0	29.2	70.8	-	100.0	39.4	60.6	-	100.0	381
Manmunai North	74.6	25.2	0.2	100.0	79.7	20.1	0.2	100.0	88.6	11.2	0.2	100.0	2947
Kattankudy	84.6	15.1	0.3	100.0	77.6	22.1	0.3	100.0	88.6	11.1	0.3	100.0	1765
Manmunai Pattu	64.0	35.8	0.2	100.0	65.4	34.3	0.3	100.0	77.2	22.4	0.4	100.0	2338
Manmunai South & Eruvilpattu	66.1	33.8	0.1	100.0	70.8	29.1	0.1	100.0	83.2	16.7	0.1	100.0	3290
<b>Total</b>	<b>57.4</b>	<b>42.5</b>	<b>0.1</b>	<b>100.0</b>	<b>60.9</b>	<b>39.0</b>	<b>0.1</b>	<b>100.0</b>	<b>70.6</b>	<b>29.2</b>	<b>0.2</b>	<b>100.0</b>	<b>13871</b>

Note: NS<sup>□</sup> - Not Stated

\* Statistics given here are only for the affected DS divisions

\*\* Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.