

Table 2.5: Percentage distribution of damaged\*\* housing units in affected DS divisions\* by material used for construction: Colombo District

Affected DS Division	Material used for roof				Material used for wall				Material used for floor				Total
	Permanent	Temporary	NS <sup>□</sup>	%	Permanent	Temporary	NS <sup>□</sup>	%	Permanent	Temporary	NS <sup>□</sup>	%	
Colombo	48.5	51.5	-	100.0	42.8	57.2	-	100.0	95.5	4.5	-	100.0	755
Thimbrigasyaya	46.3	53.7	-	100.0	20.4	79.6	-	100.0	90.7	9.3	-	100.0	62
Dehiwala	52.6	47.4	-	100.0	42.0	58.0	-	100.0	99.8	0.2	-	100.0	462
Rathmalana	55.7	44.1	0.2	100.0	40.5	59.3	0.2	100.0	98.9	0.9	0.2	100.0	669
Moratuwa	62.0	37.9	0.1	100.0	41.4	58.6	-	100.0	96.5	3.4	0.1	100.0	5050
<b>Total</b>	<b>58.8</b>	<b>41.1</b>	<b>0.1</b>	<b>100.0</b>	<b>41.3</b>	<b>58.6</b>	<b>0.1</b>	<b>100.0</b>	<b>96.8</b>	<b>3.1</b>	<b>0.1</b>	<b>100.0</b>	<b>6998</b>

Note: NS<sup>□</sup> - Not Stated

\* Statistics given here are only for the affected DS divisions

\*\* Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.