

Table 2.5: Percentage distribution of damaged** housing units in affected DS divisions* by material used for construction: Matara District

Affected DS Division	Material used for roof				Material used for wall				Material used for floor				Total
	Permanent	Temporary	NS [□]	Total	Permanent	Temporary	NS [□]	Total	Permanent	Temporary	NS [□]	Total	
Weligama	87.2	12.7	0.1	100.0	85.7	14.2	0.1	100.0	94.4	5.5	0.1	100.0	2810
Matara Four Gravets	90.4	9.5	0.1	100.0	89.4	10.5	0.1	100.0	96.2	3.6	0.2	100.0	2361
Devinuwara	87.9	12.1	-	100.0	87.4	12.6	-	100.0	95.5	4.5	-	100.0	412
Dickwella	93.0	6.9	0.1	100.0	93.9	6.0	0.1	100.0	95.2	4.7	0.1	100.0	971
Total	89.2	10.7	0.1	100.0	88.3	11.6	0.1	100.0	95.2	4.7	0.1	100.0	6554

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.