

Table 2.5: Percentage distribution of damaged** housing units in affected DS divisions* by material used for construction: Mullativu District

Type of damaged	Material used for roof				Material used for wall				Material used for floor				Total
	Permanent	Temporary	NS [□]	%	Permanent	Temporary	NS [□]	%	Permanent	Temporary	NS [□]	%	
Maritimepattu	27.6	72.3	0.1	100.0	32.3	67.6	0.2	100.0	34.8	65.0	0.2	100.0	5700
Total	27.6	72.3	0.1	100.0	32.3	67.6	0.2	100.0	34.8	65.0	0.2	100.0	5700

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.