

Table 2.5: Percentage distribution of damaged** housing units in affected DS divisions* by material used for construction: Hambantota District

Affected DS Division	Material used for roof				Material used for wall				Material used for floor				Total
	Permanent	Temporary	NS [□]	%	Permanent	Temporary	NS [□]	%	Permanent	Temporary	NS [□]	%	
Tissamaharamaya	83.5	14.8	1.7	100.0	92.0	8.0	-	100.0	87.5	11.4	1.1	100.0	210
Hambantota	96.8	3.0	0.2	100.0	96.2	3.8	-	100.0	97.8	2.0	0.2	100.0	782
Ambalantota	71.8	28.2	-	100.0	76.3	23.7	-	100.0	73.4	26.6	-	100.0	190
Tangalle	91.3	8.6	0.1	100.0	90.7	9.2	0.1	100.0	94.7	5.2	0.1	100.0	1359
Total	90.7	9.1	0.2	100.0	91.3	8.7	0.0	100.0	93.2	6.6	0.2	100.0	2541

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.