

Table 2.5: Percentage distribution of damaged** housing units in affected DS divisions* by material used for construction: Galle District

Affected DS Division	Material used for roof				Material used for wall				Material used for floor				Total
	Permanent	Temporary	NS [□]	Total	Permanent	Temporary	NS [□]	Total	Permanent	Temporary	NS [□]	Total	
	%	%	%	%	%	%	%	%	%	%	%	%	
Bentota	87.2	12.8	-	100.0	76.9	23.1	-	100.0	89.7	10.3	-	100.0	46
Balapitiya	88.2	11.6	0.2	100.0	85.5	14.3	0.2	100.0	95.2	4.5	0.3	100.0	2574
Ambalangoda	88.5	11.5	0.0	100.0	75.6	24.2	0.2	100.0	95.6	4.2	0.2	100.0	595
Hikkaduwa	86.2	13.6	0.2	100.0	84.7	15.1	0.2	100.0	94.5	5.3	0.2	100.0	5696
Galle Four Gravets	82.9	17.0	0.1	100.0	81.2	18.5	0.3	100.0	96.1	3.7	0.2	100.0	2066
Habaraduwa	86.3	13.5	0.2	100.0	85.4	14.5	0.1	100.0	91.2	8.6	0.2	100.0	1668
Total	86.2	13.6	0.2	100.0	83.9	15.9	0.2	100.0	94.5	5.3	0.2	100.0	12645

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.