

Table 2.5: Percentage distribution of damaged\*\* housing units in affected DS divisions\* by material used for construction: Gampaha District

Affected DS Division	Material used for roof				Material used for wall				Material used for floor				Total
	Permanent	Temporary	NS <sup>□</sup>	Total	Permanent	Temporary	NS <sup>□</sup>	Total	Permanent	Temporary	NS <sup>□</sup>	Total	
	%	%	%	%	%	%	%	%	%	%	%	%	
Negombo	48.0	52.0	0.0	100.0	44.4	55.6	0.0	100.0	87.1	12.7	0.2	100.0	679
Wattala	46.4	53.3	0.3	100.0	39.6	60.1	0.3	100.0	90.6	8.8	0.6	100.0	327
<b>Total</b>	<b>47.5</b>	<b>52.4</b>	<b>0.1</b>	<b>100.0</b>	<b>42.9</b>	<b>57.0</b>	<b>0.1</b>	<b>100.0</b>	<b>88.3</b>	<b>11.4</b>	<b>0.3</b>	<b>100.0</b>	<b>1006</b>

Source: Department of Census and Statistics

Note: NS<sup>□</sup> - Not Stated

\* Statistics given here are only for the affected DS divisions

\*\* Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.