

Table 2.5: Percentage distribution of damaged\*\* housing units in affected DS divisions\* by material used for construction: Jaffna District

Affected DS Division	Material used for roof				Material used for wall				Material used for floor				Total
	Permanent	Temporary	NS <sup>□</sup>	Total	Permanent	Temporary	NS <sup>□</sup>	Total	Permanent	Temporary	NS <sup>□</sup>	Total	
	%	%	%	%	%	%	%	%	%	%	%	%	
Vadamarachchi East	66.0	34.0	-	100.0	78.7	21.2	0.1	100.0	79.7	20.2	0.1	100.0	3549
Vadamarachchi North	73.9	26.1	-	100.0	78.4	21.6	-	100.0	82.3	17.7	-	100.0	2660
<b>Total</b>	<b>69.4</b>	<b>30.6</b>	<b>-</b>	<b>100.0</b>	<b>78.6</b>	<b>21.4</b>	<b>-</b>	<b>100.0</b>	<b>80.7</b>	<b>19.2</b>	<b>0.1</b>	<b>100.0</b>	<b>6209</b>

Source: Department of Census and Statistics

Note: NS<sup>□</sup> - Not Stated

\* Statistics given here are only for the affected DS divisions

\*\* Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.