

Table 2.5: Percentage distribution of damaged** housing units in affected DS divisions* by material used for construction: Kalutara District

Affected DS Division	Material used for roof				Material used for wall				Material used for floor				Total
	Permanent	Temporary	NS [□]	Total	Permanent	Temporary	NS [□]	Total	Permanent	Temporary	NS [□]	Total	
	%	%	%	%	%	%	%	%	%	%	%	%	
Panadura	77.5	22.2	0.3	100.0	70.6	29.1	0.3	100.0	97.3	2.4	0.3	100.0	2406
Kalutara	84.8	15.1	0.1	100.0	78.2	21.7	0.1	100.0	96.5	3.4	0.1	100.0	2228
Beruwala	91.7	8.2	0.1	100.0	90.7	9.1	0.2	100.0	98.4	1.5	0.1	100.0	2063
Total	84.3	15.5	0.2	100.0	79.4	20.5	0.1	100.0	97.4	2.4	0.2	100.0	6697

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.