

**Table 1.7 : Distribution of damaged housing units in the affected GN divisions by type of damage and distance to the sea
: Rathmalana DS Division of Colombo District**

Affected GN Division	Completely Damaged				Partially damaged (Unusable)				Partially damaged (Usable)				Total			
	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total
Mountlavenia	177	1	0	178	22	0	0	22	80	2	0	82	279	3	0	282
Wedikanda	44	2	0	46	30	0	0	30	74	3	0	77	148	5	0	153
Rathmalana West	10	0	0	10	5	0	0	5	39	0	0	39	54	0	0	54
Vihara	39	0	0	39	29	0	0	29	112	0	0	112	180	0	0	180
D.S. Div. Total	270	3	0	273	86	0	0	86	305	5	0	310	661	8	0	669

Source: Department of Census and Statistics.