

Table 2.1a: Percentage distribution of *completely damaged housing units* in affected DS divisions* by highest height submerged by sea water : Colombo District

Affected DS Division	Highest height submerged (feet)								
	Less than or equal to 5	6 - 7	8 - 10	11 - 20	21 - 30	More than 30	NS [□]	Total	
	%	%	%	%	%	%	%	No.	%
Colombo	15.0	28.1	47.7	5.9	-	-	3.3	162	100.0
Thimbirigasyaya	23.1	38.5	38.4	-	-	-	-	13	100.0
Dehiwala	19.1	52.0	18.5	10.1	-	-	0.3	333	100.0
Rathmalana	20.6	43.5	31.7	3.4	-	-	0.8	273	100.0
Moratuwa	17.3	31.9	32.9	17.8	-	-	0.1	2532	100.0
Total	17.8	35.0	32.1	14.8	-	-	0.3	3313	100.0

Source: Department of Census and Statistics

Table 2.1b: Percentage distribution of *partially damaged housing units (unusable)* in affected DS divisions* by highest height submerged by sea water : Colombo District

Affected DS Division	Highest height submerged (feet)								
	Less than or equal to 5	6 - 7	8 - 10	11 - 20	21 - 30	More than 30	NS [□]	Total	
	%	%	%	%	%	%	%	No.	%
Colombo	41.5	42.7	12.2	1.2	-	-	2.4	88	100.0
Thimbirigasyaya	8.4	83.3	-	-	-	-	8.3	17	100.0
Dehiwala	5.9	50.0	26.5	17.6	-	-	-	37	100.0
Rathmalana	53.6	39.3	7.1	-	-	-	-	86	100.0
Moratuwa	42.6	29.5	18.5	9.1	-	-	0.3	418	100.0
Total	41.0	35.6	15.8	6.8	-	-	0.8	646	100.0

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.