

Table 2.2a: Percentage distribution of *completely damaged housing units* in affected DS divisions* by condition of the toilet facilities : Colombo District

| Affected DS Division | Condition of the toilet facility | | | | | Total | |
|----------------------|----------------------------------|-------------|-------------|-----------------|-------------|--------------|--|
| | Damaged | Not damaged | No latrine | NS [□] | Total | | |
| | % | % | % | % | No. | % | |
| Colombo | 43.8 | 11.8 | 43.7 | 0.7 | 162 | 100.0 | |
| Thimbirigasyaya | 15.4 | - | 84.6 | - | 13 | 100.0 | |
| Dehiwala | 28.8 | 6.4 | 64.8 | - | 333 | 100.0 | |
| Rathmalana | 27.5 | 14.1 | 58.4 | - | 273 | 100.0 | |
| Moratuwa | 57.1 | 10.0 | 32.9 | - | 2532 | 100.0 | |
| Total | 50.2 | 10.1 | 39.7 | - | 3313 | 100.0 | |

Source: Department of Census and Statistics

Table 2.2b: Percentage distribution of *partially damaged housing units (unusable)* in affected DS divisions* by condition of the toilet facilities : Colombo District

| Affected DS Division | Condition of the toilet facility | | | | | Total | |
|----------------------|----------------------------------|-------------|-------------|-----------------|------------|--------------|--|
| | Damaged | Not damaged | No latrine | NS [□] | Total | | |
| | % | % | % | % | No. | % | |
| Colombo | 31.7 | 24.4 | 43.9 | - | 88 | 100.0 | |
| Thimbirigasyaya | 25.0 | - | 75.0 | - | 17 | 100.0 | |
| Dehiwala | 32.4 | 29.4 | 38.2 | - | 37 | 100.0 | |
| Rathmalana | 31.0 | 28.5 | 40.5 | - | 86 | 100.0 | |
| Moratuwa | 40.1 | 30.7 | 29.2 | - | 418 | 100.0 | |
| Total | 36.5 | 28.6 | 34.9 | - | 646 | 100.0 | |

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.

Table 2.2c: Percentage distribution of *partially damaged housing units (usable)* in affected DS divisions* by condition of the toilet facilities : Colombo District

| Affected DS Division | Condition of the toilet facility | | | | | Total | |
|----------------------|----------------------------------|-------------|-------------|-----------------|-------------|--------------|--|
| | Damaged | Not damaged | No latrine | NS [□] | Total | | |
| | % | % | % | % | No. | % | |
| Colombo | 13.5 | 42.9 | 43.2 | 0.4 | 505 | 100.0 | |
| Thimbirigasyaya | 34.5 | 3.4 | 62.1 | - | 32 | 100.0 | |
| Dehiwala | 28.0 | 48.0 | 24.0 | - | 92 | 100.0 | |
| Rathmalana | 26.8 | 33.9 | 39.3 | - | 310 | 100.0 | |
| Moratuwa | 26.4 | 56.2 | 17.4 | - | 2100 | 100.0 | |
| Total | 24.2 | 50.3 | 25.4 | 0.1 | 3039 | 100.0 | |

Source: Department of Census and Statistics