

Table 1.10: Distribution of damaged housing units in the affected GN divisions by type of damage and distance to the sea : Alayadiwembu DS Division of Ampara District

Affected GN Division	Completely Damaged				Partially damaged (Unusable)				Partially damaged (Usable)				Total			
	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total
Akkaraipattu -09	0	12	0	12	0	2	0	2	0	5	0	5	0	19	0	19
Sinna Muhathuvaram	212	0	0	212	36	0	0	36	61	0	0	61	309	0	0	309
D.S. Div. Total	212	12	0	224	36	2	0	38	61	5	0	66	309	19	0	328

Source: Department of Census and Statistics.