

**Table 1.13: Distribution of damaged housing units in the affected GN divisions by type of damage and distance to the sea : Lahugala DS Division of Ampara District**

Affected GN Division	Completely Damaged				Partially damaged (Unusable)				Partially damaged (Usable)				Total			
	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total
Sasthiriwela	0	0	0	0	0	0	0	0	0	6	0	6	0	6	0	6
Panama North	0	0	0	0	0	0	0	0	0	8	0	8	0	8	0	8
Panama South	4	0	0	4	1	2	0	3	1	11	0	12	6	13	0	19
<b>D.S. Div. Total</b>	<b>4</b>	<b>0</b>	<b>0</b>	<b>4</b>	<b>1</b>	<b>2</b>	<b>0</b>	<b>3</b>	<b>1</b>	<b>25</b>	<b>0</b>	<b>26</b>	<b>6</b>	<b>27</b>	<b>0</b>	<b>33</b>

Source: Department of Census and Statistics.