

Table 1.2: Percentage distribution of housing units surveyed and total housing units listed by type of damage in affected DS divisions : Ampara District

Affected DS Division	Percentage of Housing Units Surveyed			%	Total Number of Damaged Housing Units Listed
	Completely Damaged	Partially Damaged (Unusable)	Partially Damaged (Usable)		
Kalmuni	44.3	13.1	42.6	100.0	7815
Sainthamaruthu	28.4	15.1	56.5	100.0	2719
Karathivu	56.6	16.3	27.1	100.0	1931
Ninthavur	26.8	17.9	55.3	100.0	1674
Addalachchenai	23.5	6.5	70.0	100.0	592
Akkaraipattu	17.5	14.8	67.7	100.0	950
Alayadiwembu	68.0	10.8	21.2	100.0	328
Thirukkovi	62.6	16.5	20.9	100.0	2953
Pothuvi	61.1	9.3	29.6	100.0	2206
Lahugala	17.4	13.0	69.6	100.0	33
Total	46.1	13.9	40.0	100.0	21201

Source: Department of Census and Statistics.