

**Table 1.6 : Distribution of damaged housing units in the affected GN divisions by type of damage and distance to the sea : Karathivu DS Division of Ampara District**

Affected GN Division	Completely Damaged				Partially damaged (Unusable)				Partially damaged (Usable)				Total			
	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total
Karaitivu Central	0	12	0	12	0	17	0	17	0	137	0	137	0	166	0	166
Karaitivu East	182	16	0	198	72	7	0	79	75	15	0	90	329	38	0	367
Karaitivu - 03	93	64	0	157	17	45	0	62	0	11	0	11	110	120	0	230
Karaitivu - 02	0	1	0	1	0	5	0	5	0	53	0	53	0	59	0	59
Karaitivu - 05	0	2	0	2	0	0	0	0	0	53	0	53	0	55	0	55
Karaitivu -04	89	12	0	101	18	35	0	53	5	22	0	27	112	69	0	181
Karaitivu -08	184	35	0	219	23	15	0	38	1	31	0	32	208	81	0	289
Karaitivu -10	0	1	0	1	0	3	0	3	0	27	0	27	0	31	0	31
Karaitivu -09	199	17	0	216	11	8	0	19	1	2	0	3	211	27	0	238
Karaitivu -11	0	9	0	9	0	9	0	9	0	183	0	183	0	201	0	201
Karaitivu -12	0	60	0	60	0	7	0	7	0	47	0	47	0	114	0	114
<b>D.S. Div. Total</b>	<b>747</b>	<b>229</b>	<b>0</b>	<b>976</b>	<b>141</b>	<b>151</b>	<b>0</b>	<b>292</b>	<b>82</b>	<b>581</b>	<b>0</b>	<b>663</b>	<b>970</b>	<b>961</b>	<b>0</b>	<b>1931</b>

Source: Department of Census and Statistics.