

**Table 1.7: Distribution of damaged housing units in the affected GN divisions by type of damage and distance to the sea : Nintavur DS Division of Ampara District**

Affected GN Division	Completely Damaged				Partially damaged (Unusable)				Partially damaged (Usable)				Total			
	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total
Nintavur-01	107	51	0	158	34	27	0	61	36	80	0	116	177	158	0	335
Nintavur-02	20	13	0	33	7	16	0	23	14	84	0	98	41	113	0	154
Nintavur-03	23	24	0	47	25	20	0	45	25	154	0	179	73	198	0	271
Nintavur-04	28	0	0	28	30	4	0	34	54	9	0	63	112	13	0	125
Nintavur-05	45	17	0	62	17	3	0	20	40	95	0	135	102	115	0	217
Nintavur-06	19	13	0	32	52	5	0	57	15	57	0	72	86	75	0	161
Nintavur-07	17	11	0	28	4	6	0	10	16	51	0	67	37	68	0	105
Nintavur-08	26	5	0	31	6	9	0	15	49	63	0	112	81	77	0	158
Nintavur-09	27	5	0	32	18	2	0	20	25	15	0	40	70	22	0	92
Nintavur-10	7	0	0	7	1	0	0	1	27	4	0	31	35	4	0	39
Nintavur-11	0	0	0	0	0	2	0	2	0	15	0	15	0	17	0	17
<b>D.S. Div. Total</b>	<b>319</b>	<b>139</b>	<b>0</b>	<b>458</b>	<b>194</b>	<b>94</b>	<b>0</b>	<b>288</b>	<b>301</b>	<b>627</b>	<b>0</b>	<b>928</b>	<b>814</b>	<b>860</b>	<b>0</b>	<b>1674</b>

Source: Department of Census and Statistics.