

Table 2.1b: Percentage distribution of *partially damaged housing units (unusable)* in affected DS divisions* by highest height submerged by sea water : Ampara District

Affected DS Division	Highest height submerged (feet)								
	Less than or equal 5	6 - 7	8 - 10	11 - 20	21 - 30	More than 30	NS [□]	Total	
	%	%	%	%	%	%	%	No.	%
Kalmuni	13.7	15.5	41.2	27.8	1.1	0.6	0.1	971	100.0
Sainthamaruthu	17.0	13.1	30.4	38.3	0.6	0.3	0.3	363	100.0
Karathivu	13.0	20.2	35.3	29.4	1.7	-	0.4	292	100.0
Ninthavur	35.9	21.1	29.5	13.1	-	-	0.4	288	100.0
Addalachchenai	51.7	34.5	10.3	-	-	-	3.5	45	100.0
Akkaraipattu	64.2	28.6	3.6	-	-	-	3.6	94	100.0
Alayadiwembu	14.7	11.8	70.6	2.9	-	-	-	38	100.0
Thirukkivil	24.8	18.6	37.3	17.6	1.0	-	0.7	496	100.0
Pothuvil	39.7	17.2	25.3	15.6	1.1	-	1.1	202	100.0
Lahugala	66.7	-	-	33.3	-	-	-	3	100.0
Total	21.7	17.2	35.3	24.1	0.9	0.3	0.5	2792	100.0

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.