

Table 1.2: Percentage distribution of housing units surveyed and total housing units listed by type of damage in affected DS divisions : Batticaloe District

Affected DS Division	Percentage of Housing Units Surveyed			%	Total Number of Damaged Housing Units Listed
	Completely Damaged	Partially Damaged (Unusable)	Partially Damaged (Usable)		
Koralaipattu North	65.4	11.6	23.0	100.0	1749
Koralaipattu	47.4	10.4	42.2	100.0	1334
Koralaipattu south	67.3	29.3	3.4	100.0	67
Eravupattu	27.7	3.3	69.0	100.0	381
Manmunai North	36.9	14.6	48.5	100.0	2947
Kattankudy	25.8	12.3	61.9	100.0	1765
Manmunai Pattu	26.3	19.2	54.5	100.0	2338
Manmunai South & Eruvil pattu	40.3	12.5	47.2	100.0	3290
Total	42.3	13.3	44.4	100.0	13871

Source: Department of Census and Statistics