

**Table 1.9 : Distribution of damaged housing units in the affected GN divisions by type of damage and distance to the sea : Kattankudy DS Division of Batticaloe District**

Affected GN Division	Completely Damaged				Partially damaged (Unusable)				Partially damaged (Usable)				Total			
	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total
New Kattankudy(S)	32	74	0	106	8	38	0	46	5	212	0	217	45	324	0	369
New Kattankudy(N)	28	80	0	108	16	40	0	56	3	303	0	306	47	423	0	470
New Kattankudy(E)	135	156	0	291	13	90	0	103	16	516	0	532	164	762	0	926
<b>D.S. Div. Total</b>	<b>195</b>	<b>310</b>	<b>0</b>	<b>505</b>	<b>37</b>	<b>168</b>	<b>0</b>	<b>205</b>	<b>24</b>	<b>1031</b>	<b>0</b>	<b>1055</b>	<b>256</b>	<b>1509</b>	<b>0</b>	<b>1765</b>

Source: Department of Census and Statistics