

Table 1.3: Distribution of damaged housing units in the affected DS divisions by type of damage and distance to the sea : Colombo District

Affected DS Division	Completely Damaged				Partially damaged (Unusable)				Partially damaged (Usable)				Total			
	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total
Colombo	159	3	0	162	79	9	0	88	431	74	0	505	669	86	0	755
Thimbirigasyaya	13	0	0	13	16	1	0	17	31	1	0	32	60	2	0	62
Dehiwala	332	1	0	333	37	0	0	37	77	15	0	92	446	16	0	462
Rathmalana	270	3	0	273	86	0	0	86	305	5	0	310	661	8	0	669
Moratuwa	2351	180	1	2532	357	61	0	418	1454	646	0	2100	4162	887	1	5050
District Total	3125	187	1	3313	575	71	0	646	2298	741	0	3039	5998	999	1	6998

Source: Department of Census and Statistics.