

Table 8.1: Percentage distribution of buildings other than housing units damaged**
in affected DS divisions * by type of damage : Colombo district

Affected DS Division	Type of damage				
	Completely damaged	Partially damaged (Unusable)	Partially damaged (Usable)	Total No. of buildings other than housing units damaged**	
	%	%	%	No.	%
Colombo	10.8	16.2	73.0	52	100.0
Thimbirigasyaya	-	33.3	66.7	15	100.0
Dehiwala	18.7	25.0	56.3	20	100.0
Rathmalana	54.2	20.8	25.0	40	100.0
Moratuwa	41.5	12.0	46.5	319	100.0
Total	36.7	14.4	48.9	446	100.0

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.