

**Table 1.4: Distribution of damaged housing units in the affected GN divisions by type of damage and distance to the sea : Bentota DS Division of Galle District**

Affected GN Division	Completely Damaged				Partially damaged (Unusable)				Partially damaged (Usable)				Total			
	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total
Athuruwella	2	0	0	2	0	0	0	0	8	6	0	14	10	6	0	16
Yalegama	0	0	0	0	0	0	0	0	6	0	0	6	6	0	0	6
Kaikawala	3	0	0	3	0	0	0	0	11	0	0	11	14	0	0	14
Kahawegammedda	1	0	0	1	1	0	0	1	8	0	0	8	10	0	0	10
<b><i>D.S. Div. Total</i></b>	<b>6</b>	<b>0</b>	<b>0</b>	<b>6</b>	<b>1</b>	<b>0</b>	<b>0</b>	<b>1</b>	<b>33</b>	<b>6</b>	<b>0</b>	<b>39</b>	<b>40</b>	<b>6</b>	<b>0</b>	<b>46</b>

Source: Department of Census and Statistics.