

Table 8.1: Percentage distribution of buildings other than housing units damaged** in affected DS divisions * by type of damage Galle District

Affected DS Division	Type of damage				
	Completely damaged	Partially damaged (Unusable)	Partially damaged (Usable)	Total No. of buildings other than housing units damaged**	
	%	%	%	No.	%
Bentota	-	11.1	88.9	13	100.0
Balapitiya	29.4	10.9	59.7	285	100.0
Ambalangoda	15.5	2.8	81.7	85	100.0
Hikkaduwa	35.7	8.5	55.8	1189	100.0
Galle Four Gravets	30.2	12.4	57.4	1272	100.0
Habaraduwa	40.0	10.1	49.9	875	100.0
Total	33.4	10.3	56.3	3719	100.0

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.