

Table 1.2: Percentage distribution of housing units surveyed and total housing units listed by type of damage in affected DS divisions : Gampaha District

Affected DS Division	Percentage of Housing Units Surveyed			%	Total number of damaged housing units listed
	Completely Damaged	Partially Damaged (Unusable)	Partially Damaged (Usable)		
Negombo	38.6	8.2	53.2	100.0	679
Wattala	8.8	9.7	81.5	100.0	327
Total	28.4	8.8	62.8	100.0	1006

Source : Department of Census and Statistics