

**Table 1.4: Distribution of damaged housing units in the affected GN divisions by type of damage and distance to the sea : Negombo DS Division of Gampaha District**

Affected GN Division	Completely Damaged				Partially damaged (Unusable)				Partially damaged (Usable)				Total			
	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total
Kammalthura	31	0	0	31	4	1	0	5	27	5	0	32	62	6	0	68
Palangathure	25	0	0	25	4	0	0	4	50	0	0	50	79	0	0	79
Kudapaduwa - North	33	1	0	34	2	0	0	2	13	0	0	13	48	1	0	49
Wellaweediya	91	6	0	97	23	3	0	26	74	10	0	84	188	19	0	207
Munnakkaraya North	68	2	0	70	9	0	0	9	96	0	0	96	173	2	0	175
Doowa	1	3	0	4	2	3	0	5	15	7	0	22	18	13	0	31
Pitipana North	0	1	0	1	0	2	0	2	0	22	0	22	0	25	0	25
Munnakkaraya	0	0	0	0	0	3	0	3	0	42	0	42	0	45	0	45
<b>D.S. Div. Total</b>	<b>249</b>	<b>13</b>	<b>0</b>	<b>262</b>	<b>44</b>	<b>12</b>	<b>0</b>	<b>56</b>	<b>275</b>	<b>86</b>	<b>0</b>	<b>361</b>	<b>568</b>	<b>111</b>	<b>0</b>	<b>679</b>

Source: Department of Census and Statistics