

Table 8.1: Percentage distribution of buildings other than housing units damaged** in affected DS divisions * by type of damage: Gampaha District

Affected DS Division	Type of damage				
	Completely damaged	Partially damaged (Unusable)	Partially damaged (Usable)	Total No. of buildings other than housing units damaged**	
	%	%	%	No.	%
Negombo	44.3	9.1	46.6	95	100.0
Wattala	-	-	100.0	5	100.0
Total	41.9	8.6	49.5	100	100.0

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.