

Table 8.6 : Percentage distribution of buildings other than housing units damaged** in affected DS divisions * by material used for construction of the unit :Jaffna District

Affected DS Division	Material used for construction				
	Permanent	Other	NS [□]	Total No. of buildings other than housing units damaged**	
	%	%	%	No.	%
Vadamarachchy East	86.5	13.5	-	159	100.0
Vadamarachchy North	90.6	8.7	0.7	203	100.0
Total	89.3	10.1	0.6	362	100.0

Source: Department of Census of Statistics

Table 8.7 : Percentage distribution of buildings other than housing units damaged** in affected DS divisions * by total floor area of the unit : Jaffna District

Affected DS Division	Total floor area (In square feet)					
	Less than 500	500 - 999	1000 or more	NS [□]	Total No. of buildings other than housing units damaged**	
	%	%	%	%	No.	%
Vadamarachchy East	67.3	5.8	25.0	1.9	159	100.0
Vadamarachchy North	62.2	26.0	11.8	-	203	100.0
Total	63.7	20.1	15.6	0.6	362	100.0

Source: Department of Census of Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.