

Table 2.5: Percentage distribution of damaged\*\* housing units in affected DS divisions\* by material used for construction: killinochchi District

Affected DS Division	Type of roof			Type of walls			Type of floor			Total
	Permanent	Temporary	%	Permanent	Temporary	%	Permanent	Temporary	%	
	%	%		%	%		%			
Panchchilaipalli	6.7	93.3	100.0	8.7	91.3	100.0	30.2	69.8	100.0	187
Kandawali	6.7	93.3	100.0	6.7	93.3	100.0	6.7	93.3	100.0	15
Poonakary	2.2	97.8	100.0	2.2	97.8	100.0	16.9	83.1	100.0	92
<b>Total</b>	5.1	94.9	100.0	6.3	93.7	100.0	24.1	75.9	100.0	294

Source: Department of Census and Statistics

Note: NS<sup>□</sup> - Not Stated

\* Statistics given here are only for the affected DS divisions

\*\* Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.