

Table 8.6 : Percentage distribution of buildings other than housing units damaged** in affected DS divisions * by material used for construction of the unit : killinochchi District

Affected DS Division	Material used for construction				
	Permanent	Other	NS ^o	Total No. of buildings other than housing units damaged**	
	%	%	%	No.	%
Pachchilapillai	83.3	16.7	-	13	100.0
Total	83.3	16.7	-	13	100.0

Source: Department of Census and Statistics

Note: NS^o - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.