

Table 2.2a: Percentage distribution of *completely damaged housing units* in affected DS divisions\* by condition of the toilet facility: Matara District

Affected DS Division	Condition of the toilet facility					Total	
	Damaged	Not damaged	No latrine	NS <sup>□</sup>			
	%	%	%	%	No.	%	
Weligama	62.2	13.4	24.3	0.1	797	100.0	
Matara Four Gravets	77.5	11.3	10.8	0.4	604	100.0	
Devinuwara	46.0	23.0	31.0	-	91	100.0	
Dickwella	67.8	12.3	19.9	-	312	100.0	
<b>Total</b>	<b>67.4</b>	<b>13.0</b>	<b>19.4</b>	<b>0.2</b>	<b>1804</b>	<b>100.0</b>	

Source: Department of Census and Statistics

Table 2.2b: Percentage distribution of *partially damaged housing units (unusable)* in affected DS divisions\* by condition of the toilet facility : Matara District

Affected DS Division	Condition of the toilet facility				Total	
	Damaged	Not damaged	No latrine	NS <sup>□</sup>		
	%	%	%	%	No.	%
Weligama	51.4	31.1	17.1	0.4	280	100.0
Matara Four Gravets	55.5	38.8	5.7	-	248	100.0
Devinuwara	56.8	27.5	15.7	-	55	100.0
Dickwella	45.8	36.7	17.5	-	125	100.0
<b>Total</b>	<b>52.2</b>	<b>34.4</b>	<b>13.3</b>	<b>0.1</b>	<b>708</b>	<b>100.0</b>

Source: Department of Census and Statistics

Note: NS<sup>□</sup> - Not Stated

\* Statistics given here are only for the affected DS divisions

\*\* Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.