

Table 2.6: Percentage distribution of the *damaged** housing units* in the affected DS divisions* by number of rooms in the unit: Matara District

Affected DS Division	Percentage of housing units by number of rooms					
	1-3	4-6	More than 6	NS [□]	Total	
	%	%	%	%	No.	%
Weligama	46.2	47.7	6.0	0.1	2810	100.0
Matara Four Gravets	41.6	51.2	7.0	0.2	2361	100.0
Devinuwara	45.5	48.2	6.3	-	412	100.0
Dickwella	38.6	51.3	9.8	0.3	971	100.0
Total	43.4	49.4	7.0	0.2	6554	100.0

Source: Department of Census and Statistics

Table 2.7: Percentage distribution of the *damaged** housing units* in the affected DS divisions* by floor area of the housing unit: Matara District

Affected DS Division	Percentage of housing units by floor area (Sq. feet)					
	< 100	100-999	1000-9999	NS [□]	Total	
	%	%	%	%	No.	%
Weligama	2.5	72.2	24.2	1.1	2810	100.0
Matara Four Gravets	1.5	65.6	31.6	1.3	2361	100.0
Devinuwara	0.8	73.3	24.4	1.5	412	100.0
Dickwella	1.1	68.3	29.4	1.2	971	100.0
Total	1.8	69.4	27.6	1.2	6554	100.0

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.