

Table 1.3: Distribution of damaged housing units in the affected DS divisions by type of damage and distance to the sea : Mullativu District

D.S. Division	Completely Damaged				Partially damaged (Unusable)				Partially damaged (Usable)				Total			
	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total
Maritimepattu	2508	2040	16	4564	315	309	3	627	152	357	0	509	2975	2706	19	5700
District Total	2508	2040	16	4564	315	309	3	627	152	357	0	509	2975	2706	19	5700

Source: Department of Census and Statistics