

**Table 1.4: Distribution of damaged housing units in the affected GN divisions by type of damage and distance to the sea : Wennappuwa DS Division of puttalam District**

Affected GN Division	Completely Damaged				Partially damaged (Unusable)				Partially damaged (Usable)				Total			
	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total
Aluthota	0	0	0	0	0	0	0	0	1	0	0	1	1	0	0	1
Sindathriya	5	0	0	5	13	0	0	13	25	3	0	28	43	3	0	46
Wellamankaraya	5	0	0	5	0	0	0	0	2	0	0	2	7	0	0	7
Kammala	2	0	0	2	2	0	0	2	0	0	0	0	4	0	0	4
<b>D.S. Div. Total</b>	<b>12</b>	<b>0</b>	<b>0</b>	<b>12</b>	<b>15</b>	<b>0</b>	<b>0</b>	<b>15</b>	<b>28</b>	<b>3</b>	<b>0</b>	<b>31</b>	<b>55</b>	<b>3</b>	<b>0</b>	<b>58</b>

Source :Department of Census and Statistics