

Table 2.1: Percentage distribution of *damaged housing unit* in Wennappuwa DS division*by highest height submerged by sea water : Puttalam District

Type of damage	Highest height submerged (feet)							Total	
	Less than or equal 5	6-7	8-10	11-20	21-30	More than 30	NS [□]	No.	%
	%	%	%	%	%	%	%		
Completely damaged	83.3	16.7	-	-	-	-	-	12	100.0
Partially damaged (Unusable)	66.7	33.3	-	-	-	-	-	15	100.0
Partially damaged (Usable)	96.6	3.4	-	-	-	-	-	31	100.0
Total	85.7	14.3	-	-	-	-	-	58	100.0

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.