

Table 2.3: Percentage distribution of damaged** housing units in affected DS divisions* by material used for construction: Puttalam District

Affected DS Division	Material used for roof				Material used for wall				Material used for floor				Total
	Permanent	Temporary	NS [□]	%	Permanent	Temporary	NS [□]	%	Permanent	Temporary	NS [□]	%	
Wennappuwa	53.6	46.4	-	100.0	67.9	32.1	-	100.0	83.9	16.1	-	100.0	58
Total	53.6	46.4	-	100.0	67.9	32.1	-	100.0	83.9	16.1	-	100.0	58

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.