

Table 2.4: Percentage distribution of *all damaged** housing units* in the affected DS divisions* by number of rooms in the unit: Puttalam District

Affected DS Division	Percentage of housing units by number of rooms					
	1-3	4-6	More than 6	NS [□]	Total	
	%	%	%	%	%	No.
Wennappuwa	83.9	16.1	-	-	100	58
Total	83.9	16.1	-	-	100	58

Source: Department of Census and Statistics

Table 2.5: Percentage distribution of *damaged** housing units* in the affected DS divisions* By floor area of the housing unit: Puttalam District

Affected DS Division	Percentage of housing units by floor area (Sq. feet)					
	< 100	100-999	1000-9999	NS [□]	Total	
	%	%	%	%	%	No.
Wennappuwa	30.4	66.0	3.6	-	100	58
Total	30.4	66.0	3.6	-	100	58

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.