

Table 1.2: Percentage distribution of housing units surveyed and total housing units listed by type of damage in affected DS divisions : Trincomalee District

Affected DS Division	Percentage of Housing Units Surveyed			%	Total Number of Damaged Housing Units Listed
	Completely Damaged	Partially Damaged (Unusable)	Partially Damaged (Usable)		
Kuchchaweli	66.1	11.3	22.6	100.0	2044
Town & Graverts	34.2	9.1	56.7	100.0	1967
Kinnia	35.9	13.4	50.7	100.0	2756
Muthur	50.7	16.1	33.2	100.0	1213
Seruwila	59.6	15.2	25.2	100.0	151
Etchalampattu	78.3	3.3	18.4	100.0	1243
Total	50.0	11.1	38.9	100.0	9374

Source: Department of Census and Statistics.