

Table 2.1b: Percentage distribution of *partially damaged housing units (unusable)* in affected DS divisions* by highest height submerged by sea water : Trincomalee District

Affected DS Division	Highest height submerged (feet)								
	Less than or equal to 5	6 - 7	8 - 10	11 - 20	21 - 30	More than 30	NS [□]	Total	
	%	%	%	%	%	%	%	No.	%
Kuchchaweli	44.9	17.4	24.2	11.1	0.5	1.9	-	231	100.0
Town & Graverts	24.7	21.1	38.5	15.1	0.6	-	-	179	100.0
Kinnia	28.5	30.9	31.8	8.4	-	-	0.4	368	100.0
Muthur	21.6	37.2	34.0	7.2	-	-	-	195	100.0
Seruwila	-	-	12.5	87.5	-	-	-	23	100.0
Etchalampattu	50.0	23.8	19.0	7.2	-	-	-	41	100.0
Total	30.0	27.3	31.1	10.9	0.2	0.4	0.1	1037	100.0

Source: Department of Census and Statistics

Table 2.1c: Percentage distribution of *partially damaged housing units (usable)* in affected DS divisions* by highest height submerged by sea water : Trincomalee District

Affected DS Division	Highest height submerged (feet)								
	Less than or equal to 5	6 - 7	8 - 10	11 - 20	21 - 30	More than 30	NS [□]	Total	
	%	%	%	%	%	%	%	No.	%
Kuchchaweli	75.2	11.1	6.2	4.3	2.4	-	0.8	461	100.0
Town & Graverts	55.2	23.1	18.7	2.7	0.1	-	0.2	1116	100.0
Kinnia	64.6	26.7	7.7	0.6	0.1	-	0.3	1399	100.0
Muthur	57.2	25.9	14.9	1.4	-	0.3	0.3	403	100.0
Seruwila	27.8	30.6	33.3	8.3	-	-	-	38	100.0
Etchalampattu	48.5	29.5	17.0	4.0	-	-	1.0	229	100.0
Total	60.7	23.9	12.6	2.1	0.3	-	0.4	3646	100.0

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.