

Table 2.2b: Percentage distribution of *partially damaged housing units (unusable)* in affected DS divisions* by condition of the toilet facilities :

Trincomalee District

Affected DS Division	Condition of the toilet facility					Total	
	Damaged	Not damaged	No latrine	NS [□]			
	%	%	%	%	No.	%	
Kuchchaweli	36.7	14.5	48.8	-	231	100.0	
Town & Graverts	31.3	16.9	51.8	-	179	100.0	
Kinnia	28.2	17.4	54.1	0.3	368	100.0	
Muthur	34.0	10.4	55.6	-	195	100.0	
Seruwila	6.3	-	93.7	-	23	100.0	
Etchalampattu	19.0	16.7	64.3	-	41	100.0	
Total	31.2	14.7	54.0	0.1	1037	100.0	

Source: Department of Census and Statistics

Table 2.2c: Percentage distribution of *partially damaged housing units (usable)* in affected DS divisions* by condition of the toilet facilities: Trincomalee District

Affected DS Division	Condition of the toilet facility					Total	
	Damaged	Not damaged	No latrine	NS [□]			
	%	%	%	%	No.	%	
Kuchchaweli	15.6	38.3	45.6	0.5	461	100.0	
Town & Graverts	20.9	43.0	36.0	-	1116	100.0	
Kinnia	17.5	47.0	35.3	0.2	1399	100.0	
Muthur	18.7	29.2	51.8	0.3	403	100.0	
Seruwila	-	-	100.0	-	38	100.0	
Etchalampattu	22.0	29.5	47.0	1.5	229	100.0	
Total	18.6	41.3	39.9	0.2	3646	100.0	

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.