

Table 2.4b: Percentage distribution of *partially damaged housing units (unusable)*, which did not have drinking water facility after Tsunami by reason for not having water by affected DS divisions* of : Trincomalee District

Affected DS Division	Main reason for not having drinking water facilities					
	Polluted well	Main line destroyed	Other	NS [□]	Total	
	%	%	%	%	No.	%
Kuchchaweli	92.7	-	6.8	0.5	231	100.0
Town & Graverts	60.6	10.1	26.3	3.0	179	100.0
Kinnia	67.4	2.2	29.1	1.3	368	100.0
Muthur	74.3	0.4	25.3	-	195	100.0
Seruwila	49.9	-	43.8	6.3	23	100.0
Etchalampattu	39.0	-	61.0	-	41	100.0
Total	72.5	2.0	24.5	1.0	1037	100.0

Source: Department of Census and Statistics

Table 2.4c: Percentage distribution of *partially damaged housing units (usable)*, which did not have drinking water facility after Tsunami by reason for not having water by affected DS divisions* of : Trincomalee District

Affected DS Division	Main reason for not having drinking water facilities					
	Polluted well	Main line destroyed	Other	NS [□]	Total	
	%	%	%	%	No.	%
Kuchchaweli	92.9	0.8	5.2	1.1	461	100.0
Town & Graverts	64.4	2.6	28.6	4.4	1116	100.0
Kinnia	71.2	2.0	25.8	1.0	1399	100.0
Muthur	64.3	1.8	33.0	0.9	403	100.0
Seruwila	5.6	-	91.6	2.8	38	100.0
Etchalampattu	38.5	-	61.5	-	229	100.0
Total	69.0	1.7	27.6	1.7	3646	100.0

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.