

Table 2.5: Percentage distribution of damaged\*\* housing units in affected DS divisions\* by material used for construction: Trincomalee District

Affected DS Division	Material used for roof				Material used for wall				Material used for floor				Total
	Permanent	Temporary	NS <sup>□</sup>	Total	Permanent	Temporary	NS <sup>□</sup>	Total	Permanent	Temporary	NS <sup>□</sup>	Total	
	%	%	%	%	%	%	%	%	%	%	%	%	
Kuchchaweli	43.3	56.5	0.2	100.0	63.5	36.3	0.2	100.0	78.2	21.6	0.2	100.0	2044
Town & Graverts	46.0	53.9	0.1	100.0	61.5	38.4	0.1	100.0	89.1	10.8	0.1	100.0	1967
Kinnia	80.0	19.8	0.2	100.0	86.8	13.0	0.2	100.0	89.7	10.0	0.3	100.0	2756
Muthur	60.6	39.3	0.1	100.0	69.7	30.1	0.2	100.0	74.6	25.1	0.3	100.0	1213
Seruwila	7.6	92.4	-	100.0	8.4	91.6	-	100.0	18.3	81.7	-	100.0	151
Etchalampattu	18.9	81.0	0.1	100.0	24.0	75.8	0.2	100.0	51.8	47.9	0.3	100.0	1243
<b>Total</b>	<b>53.3</b>	<b>46.6</b>	<b>0.1</b>	<b>100.0</b>	<b>64.7</b>	<b>35.1</b>	<b>0.2</b>	<b>100.0</b>	<b>78.8</b>	<b>21.0</b>	<b>0.2</b>	<b>100.0</b>	<b>9374</b>

Source: Department of Census and Statistics

Note: NS<sup>□</sup> - Not Stated

\* Statistics given here are only for the affected DS divisions

\*\* Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.