

**Table 1.3: Distribution of damaged housing units in the affected DS divisions by type of damage and distance to the sea
:Hambantota District**

Affected DS Division	Completely Damaged				Partially damaged (Unusable)				Partially damaged (Usable)				Total			
	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total	Within or on the 100m boundary line	Outside the 100m boundary line	Not Identified	Total
Thissamaharamaya	25	101	6	132	2	23	1	26	3	49	0	52	30	173	7	210
Hambanthota	201	320	28	549	9	44	2	55	38	138	2	178	248	502	32	782
Ambalantota	41	63	0	104	12	9	0	21	2	62	1	65	55	134	1	190
Tangalle	250	177	6	433	109	90	3	202	240	474	10	724	599	741	19	1359
<i>District Total</i>	517	661	40	1218	132	166	6	304	283	723	13	1019	932	1550	59	2541

Source: Department of Census and Statistics.