

Table 2.3a: Percentage distribution of *completely damaged housing units* in affected DS divisions* by availability of drinking water facilities after Tsunami Hambantota District

DS Division	Availability of drinking water facilities after Tsunami				
	Available	Non available	NS [□]	Total	
	%	%	%	No.	%
Thissamaharamaya	8.0	92.0	-	132	100.0
Hambantota	2.4	97.6	-	549	100.0
Ambalantota	52.0	48.0	-	104	100.0
Tangalle	33.7	66.0	0.3	433	100.0
Total	19.3	80.6	0.1	1218	100.0

Source: Department of Census and Statistics

Table 2.3b: Percentage distribution of *partially damaged housing units (unusable)* in affected DS divisions* by availability of drinking water facilities after Tsunami : Hambantota District

Affected DS Division	Availability of drinking water facilities after Tsunami				
	Available	Non available	NS [□]	Total	
	%	%	%	No	%
Thissamaharamaya	25.0	75.0	-	26	100.0
Hambantota	42.6	57.4	-	55	100.0
Ambalantota	66.7	33.3	-	21	100.0
Tangalle	50.3	49.7	-	202	100.0
Total	48.5	51.5	-	304	100.0

Source: Department of Census and Statistics

Table 2.3c: Percentage distribution of *partially damaged housing units (usable)* in affected DS divisions* by availability of drinking water facilities after Tsunami : Hambantota District

Affected DS Division	Availability of drinking water facilities after Tsunami				
	Available	Non available	NS [□]	Total	
	%	%	%	No.	%
Thissamaharamaya	61.7	38.3	-	52	100.0
Hambantota	63.1	36.9	-	178	100.0
Ambalantota	93.2	6.8	-	65	100.0
Tangalle	67.2	32.5	0.3	724	100.0
Total	68.0	31.8	0.2	1019	100.0

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.