

Table 2.6: Percentage distribution of the *damaged** housing units* in the affected DS divisions* by number of rooms in the unit: Hambantota District

Affected DS Division	Percentage of housing units by number of rooms					
	1-3	4-6	More than 6	NS [□]	Total	
	%	%	%	%	No.	%
Tissamaharamaya	63.7	30.1	5.1	1.1	210	100.0
Hambantota	41.8	51.8	6.4	-	782	100.0
						100.0
Ambalantota	59.3	36.7	4.0	-	190	100.0
Tangalle	39.0	53.8	6.9	0.3	1359	100.0
Total	43.5	50.0	6.3	0.2	2541	100.0

Source: Department of Census and Statistics

Table 2.7: Percentage distribution of the *damaged** housing units* in the affected DS divisions* By floor area of the housing unit: Hambantota District

Affected DS Division	Percentage of housing units by floor area (Sq. feet)					
	< 100	100-999	1000-9999	NS [□]	Total	
	%	%	%	%	No.	%
Tissamaharamaya	1.1	85.3	13.6	-	210	100.0
Hambantota	-	72.3	26.1	1.6	782	100.0
						100.0
Ambalantota	1.7	87.0	11.3	-	190	100.0
Tangalle	1.0	72.3	25.3	1.4	1359	100.0
Total	0.8	74.6	23.4	1.2	2541	100.0

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.