

Table 8.1: Percentage distribution of buildings other than housing units damaged\*\* in affected DS divisions \* by type of damage : Hambantota District

Affected DS Division	Type of damage				
	Completely damaged	Partially damaged (Unusable)	Partially damaged (Usable)	Total No. of buildings other than housing units damaged**	
	%	%	%	No.	%
Tissamaharamaya	89.4	2.9	7.7	118	100.0
Hambantota	66.0	6.9	27.1	340	100.0
Ambalantota	83.3	-	16.7	14	100.0
Tangalle	30.4	9.5	60.1	318	100.0
<b>Total</b>	<b>54.1</b>	<b>7.3</b>	<b>38.6</b>	<b>790</b>	<b>100.0</b>

Source: Department of Census and Statistics

Table 8.2: Percentage distribution of buildings other than housing units damaged\*\* in affected DS divisions \* by distance from the sea to the building units : Hambantota District

Affected DS Division	Distance from the sea (In meters)						Total No. of buildings other than housing units damaged**	
	Less than or equal to 100	101 - 200	201 - 300	301 or more	NS <sup>□</sup>			
	%	%	%	%	%	No.	%	
Tissamaharamaya	71.2	9.6	9.6	9.6	-	118	100.0	
Hambantota	45.4	24.3	15.6	14.7	-	340	100.0	
Ambalantota	100.0	-	-	-	-	14	100.0	
Tangalle	41.7	16.5	32.6	8.8	0.4	318	100.0	
<b>Total</b>	<b>48.7</b>	<b>18.0</b>	<b>22.1</b>	<b>11.0</b>	<b>0.2</b>	<b>790</b>	<b>100.0</b>	

Source: Department of Census and Statistics

Note: NS<sup>□</sup> - Not Stated

\* Statistics given here are only for the affected DS divisions

\*\* Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.