

Table 8.6 : Percentage distribution of buildings other than housing units damaged** in affected DS divisions * by material used for construction of the unit :Hambantota District

Affected DS Division	Material used for construction				
	Permanent	Other	NS [□]	Total No. of buildings other than housing units damaged**	
				%	%
Tissamaharamaya	31.7	67.3	1.0	118	100.0
Hambantota	81.6	17.9	0.5	340	100.0
Ambalantota	100.0	-	-	14	100.0
Tangalle	85.4	13.9	0.7	318	100.0
Total	74.8	24.5	0.7	790	100.0

Source: Department of Census and Statistics

Table 8.7 : Percentage distribution of buildings other than housing units damaged** in affected DS divisions * by total floor area of the unit : Hambantota District

Affected DS Division	Total floor area (In square feet)				Total No. of buildings other than housing units damaged**	
	Less than 500	500 - 999	1000 or more	NS [□]	No.	%
Tissamaharamaya	80.8	9.6	9.6	-	118	100.0
Hambantota	65.1	19.3	14.7	0.9	340	100.0
Ambalantota	16.7	50.0	33.3	-	14	100.0
Tangalle	51.7	21.6	26.0	0.7	318	100.0
Total	61.2	19.0	19.1	0.7	790	100.0

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.