

Table 1.9: Distribution of damaged housing units in the affected GN divisions by type of damage and distance to the sea : Akkaraipattu DS Division of Ampara District

Affected GN Division	Completely Damaged				Partially damaged (Unusable)				Partially damaged (Usable)				Total			
	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total	Within or on the 200m boundary line	Outside the 200m boundary line	Not Identified	Total
Akkaraipattu - 14	1	25	0	26	0	13	0	13	1	81	0	82	2	119	0	121
Akkaraipattu - 13	6	8	0	14	2	2	0	4	16	74	0	90	24	84	0	108
Akkaraipattu - 11	13	4	0	17	14	5	0	19	39	49	0	88	66	58	0	124
Akkaraipattu - 01	5	7	0	12	6	7	0	13	8	27	0	35	19	41	0	60
Town Division - 3	22	16	0	38	18	8	0	26	47	85	0	132	87	109	0	196
Town Division - 5	63	0	0	63	19	0	0	19	53	206	0	259	135	206	0	341
D.S. Div. Total	110	60	0	170	59	35	0	94	164	522	0	686	333	617	0	950

Source: Department of Census and Statistics.