

Table 2.1c: Percentage distribution of *partially damaged housing units (usable)* in affected DS divisions* by highest height submerged by sea water : Ampara District

| Affected DS Division | Highest height submerged (feet) | | | | | | | | Total | |
|----------------------|---------------------------------|-------------|-------------|------------|------------|--------------|-----------------|-------------|--------------|--|
| | Lesthan or equal 5 | 6 - 7 | 8 - 10 | 11 - 20 | 21 - 30 | More than 30 | NS [□] | No. | % | |
| | % | % | % | % | % | % | % | | | |
| Kalmuni | 54.7 | 19.4 | 21.4 | 4.1 | 0.2 | - | 0.2 | 3106 | 100.0 | |
| Sainthamaruthu | 64.3 | 15.3 | 13.3 | 6.7 | - | 0.2 | 0.2 | 1578 | 100.0 | |
| Karathivu | 73.2 | 11.5 | 10.5 | 3.5 | - | - | 1.3 | 663 | 100.0 | |
| Ninthavur | 78.7 | 15.2 | 4.4 | 1.2 | - | - | 0.5 | 928 | 100.0 | |
| Addalachchenai | 90.7 | 4.2 | 2.9 | 1.0 | 0.6 | 0.3 | 0.3 | 424 | 100.0 | |
| Akkaraipattu | 96.2 | 1.5 | 1.5 | - | - | - | 0.8 | 686 | 100.0 | |
| Alayadiwembu | 44.6 | 10.8 | 41.5 | 3.1 | - | - | - | 66 | 100.0 | |
| Thirukkovil | 56.1 | 24.8 | 12.0 | 6.1 | 0.6 | 0.2 | 0.2 | 680 | 100.0 | |
| Pothuvil | 78.0 | 9.4 | 7.7 | 2.3 | 0.2 | - | 2.4 | 679 | 100.0 | |
| Lahugala | 100.0 | - | - | - | - | - | - | 26 | 100.0 | |
| Total | 64.8 | 16.1 | 14.3 | 4.0 | 0.2 | 0.1 | 0.5 | 8836 | 100.0 | |

Source: Department of Census and Statistics

Note: NS[□] - Not Stated

* Statistics given here are only for the affected DS divisions

** Damaged – Completely damaged, Partially damaged (Unusable), Partially damaged (Usable) building units only were considered damaged.